

Motor-Achsen




- Alu-Schienen
- Trapezgewindespindel
- Stepper-Motor
- Coupling
- Schlitten

Parts list

- Alu-extrusions
 - 2 x Profil_5_80x20_L=80
- 3D-printed parts
 - 4 x mcs_endkappe_kreuzschlitten_80x20
- Screws (DIN 7984)
 - 16 x *M5x10mm*
 - Madenschraube DIN 914 M3 x 4 mm
- Nuts (DIN 7984)
 - 4 x Mutter tr8
- Igus
 - 8 x Gleitlager JFM_0810_10_1

Assembly

Kreuzschlitten



1. Put two Gleitlager into the second-biggest holes of each mcs endkappe so that their rim fits into the depressions in the endkappe
2. Attach two mcs endkappe to each of the Profile